


MODEL 1000DCV

REPAIR KITS for 4" to 10"





8	D4	Mission	L
Ames	Pari	MIIIII	ners

Item #	Description	Qty.	4"	6"	8"	10"
1.	Knuckle Joint Assembly	1	7015550	7015551	7015552	7015552
	(Complete Unit)					
2.	Clapper Plate with Attached Link	1	7011411	7011412	7011413	7011413
3.	Spring		7011320	7011128	7011323	7011323
	4", 6" Knuckle Joint Assembly	2 Springs Req'd				
	8", 10" Knuckle Joint Assembly	3 Springs Req'd				
4.	3/8" Stainless Steel Bolts	2	7014619	7014619	7014619	7014619
5.	Washer (not shown)	2	7014585	7014585	7014585	7014585
6.	Bronze Seat (Replaceable in line)	1	7011160	7011162	7011163	7011163
7.	Seat O-ring	1	7011161	A300704	A300706	A300706
8.	Vent Screw	1	7011133	7011133	7011133	7011133
9.	Bonnet Gasket	1	7011123	7011124	7011125	7011125
10.	Clapper Retainer Clip (not shown)	1	7013911	7013912	7013913	7013913