


American Backflow Specialties

(800) 66-BKFLO (619) 527-2525 Fax: (619) 527-2527
www.americanbackflow.com



Series 700 Double Check Valve Assembly (3/4" through 4")




FEATURES

- Replaceable seats.
- Contained Springs.
- 3/4" to 2" not repairable in-line.


DESCRIPTION

Watts Model 700 is a double check assembly that was produced from around 1973 to 1985. It is an in-line modular design with replaceable check seats. Springs are contained when the model is disassembled.

INSTALLATION



REPAIR PARTS & KITS



Ordering # Kit # Size

Rubber Parts Kits - Include all items marked *

881210	1-BFP-RK	3/4"
881215	2-BFP-RK	1"
881220	3-BFP-RK	1-1/2" - 2"

Service Parts Kits (Include complete 1st & 2nd Check Modules)



881460	4-BFP-RK	3/4"
881461	5-BFP-RK	1" (Seat not included)

2 1/2" - 4"

Ordering # Kit # Size

Rubber Parts Kits - Include all items marked *


881222	7-BFP-RK	2-1/2" - 3"
881227	8-BFP-RK	4"



Ordering # Kit # Size

Service Parts Kits (Include complete 1st & 2nd Check Modules)

881463	9-BFP-RK	2-1/2" - 3"
881464	10-BFP-RK	4"



14
Watts
Rainbird